# Product Change Notification (PCN)
# Product Discontinuance Notification (PDN)

| | | | |
|---|---|---|---|
| **PCN Number:** | 2025-0006 | **PCN Date:** | 09/24/2025 |
| **Title:** | Obsolescence and Replacements for SCM9B-xxxx | | |
| **Contact:** | Customer Service | **Phone:** | (520) 741-1404 |
| **Last Date to Order:** | Until inventory is depleted | **Last Date to Ship:** | Until inventory is depleted |
| **Change Type:** | Product Withdrawal - End Of Life - Obsolescence | | |

## Product Withdrawal/Discontinuance Notification Details

### Description of Withdrawal/Discontinuance:

Dataforth Corporation is announcing the product withdrawal and obsolescence of all SCM9B-xxxx devices. Please see below for replacement devices, as applicable.

### Reason for Withdrawal/Discontinuance:

The subcontractor manufacturing location has announced the discontinuance of these devices.

### Product Affected:

| Affected Device | Replacement Device |
|---|---|
| SCM9B-1101 | None Available |
| SCM9B-1102 | None Available |
| SCM9B-1111 | None Available |
| SCM9B-1112 | None Available |
| SCM9B-1121 | None Available |
| SCM9B-1122 | None Available |
| SCM9B-1131 | None Available |
| SCM9B-1132 | None Available |
| SCM9B-1141 | None Available |
| SCM9B-1142 | None Available |
| SCM9B-1151 | None Available |
| SCM9B-1152 | None Available |
| SCM9B-1211 | None Available |
| SCM9B-1221 | None Available |
| SCM9B-1222 | None Available |
| SCM9B-1231 | None Available |

3331 East Hemisphere Loop • Tucson, Arizona 85706 • (520) 741-1404 • FAX (520) 741-0762
E-Mail: sales@dataforth.com • Website: www.dataforth.com

Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

| | |
|---|---|
| SCM9B-1232 | None Available |
| SCM9B-1241 | None Available |
| SCM9B-1242 | None Available |
| SCM9B-1251 | None Available |
| SCM9B-1252 | None Available |
| SCM9B-1311 | None Available |
| SCM9B-1312 | None Available |
| SCM9B-1321 | None Available |
| SCM9B-1322 | None Available |
| SCM9B-1331 | None Available |
| SCM9B-1332 | None Available |
| SCM9B-1341 | None Available |
| SCM9B-1342 | None Available |
| SCM9B-1351 | None Available |
| SCM9B-1352 | None Available |
| SCM9B-1361 | None Available |
| SCM9B-1362 | None Available |
| SCM9B-1371 | None Available |
| SCM9B-1372 | None Available |
| SCM9B-1381 | None Available |
| SCM9B-1382 | None Available |
| SCM9B-1411 | None Available |
| SCM9B-1412 | None Available |
| SCM9B-1421 | None Available |
| SCM9B-1422 | None Available |
| SCM9B-1431 | None Available |
| SCM9B-1432 | None Available |
| SCM9B-1451 | None Available |
| SCM9B-1452 | None Available |
| SCM9B-1461 | None Available |
| SCM9B-1462 | None Available |
| SCM9B-1511 | None Available |
| SCM9B-1512 | None Available |
| SCM9B-1521 | None Available |
| SCM9B-1522 | None Available |
| SCM9B-1531 | None Available |
| SCM9B-1532 | None Available |
| SCM9B-1541 | None Available |
| SCM9B-1542 | None Available |



Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

| | |
|---|---|
| SCM9B-1562 | None Available |
| SCM9B-1601 | None Available |
| SCM9B-1602 | None Available |
| SCM9B-1612 | None Available |
| SCM9B-1621 | None Available |
| SCM9B-1622 | None Available |
| SCM9B-1631 | None Available |
| SCM9B-1632 | None Available |
| SCM9B-1642 | None Available |
| SCM9B-1701 | None Available |
| SCM9B-1702 | None Available |
| SCM9B-1711 | None Available |
| SCM9B-1712 | None Available |
| SCM9B-2101 | None Available |
| SCM9B-2102 | None Available |
| SCM9B-2111 | None Available |
| SCM9B-2112 | None Available |
| SCM9B-2121 | None Available |
| SCM9B-2122 | None Available |
| SCM9B-2131 | None Available |
| SCM9B-2132 | None Available |
| SCM9B-2141 | None Available |
| SCM9B-2142 | None Available |
| SCM9B-2151 | None Available |
| SCM9B-2152 | None Available |
| SCM9B-2211 | None Available |
| SCM9B-2242 | None Available |
| SCM9B-2251 | None Available |
| SCM9B-2252 | None Available |
| SCM9B-2511 | None Available |
| SCM9B-2512 | None Available |
| SCM9B-2521 | None Available |
| SCM9B-2522 | None Available |
| SCM9B-2532 | None Available |
| SCM9B-2541 | None Available |
| SCM9B-2551 | None Available |
| SCM9B-2552 | None Available |
| SCM9B-2561 | None Available |
| SCM9B-2601 | None Available |



Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

| | |
|---|---|
| SCM9B-2602 | None Available |
| SCM9B-2631 | None Available |
| SCM9B-2632 | None Available |
| SCM9B-3121 | None Available |
| SCM9B-3122 | None Available |
| SCM9B-3131 | None Available |
| SCM9B-3132 | None Available |
| SCM9B-3141 | None Available |
| SCM9B-3142 | None Available |
| SCM9B-3171 | None Available |
| SCM9B-3172 | None Available |
| SCM9B-3181 | None Available |
| SCM9B-3182 | None Available |
| SCM9B-3251 | None Available |
| SCM9B-3252 | None Available |
| SCM9B-3261 | None Available |
| SCM9B-3262 | None Available |
| SCM9B-4122 | None Available |
| SCM9B-4132 | None Available |
| SCM9B-4141 | None Available |
| SCM9B-4142 | None Available |
| SCM9B-4161 | None Available |
| SCM9B-4171 | None Available |
| SCM9B-4172 | None Available |
| SCM9B-4181 | None Available |
| SCM9B-4182 | None Available |
| SCM9B-4251 | None Available |
| SCM9B-4252 | None Available |
| SCM9B-4261 | None Available |
| SCM9B-4262 | None Available |
| SCM9B-5111 | None Available |
| SCM9B-5112 | None Available |
| SCM9B-5121 | None Available |
| SCM9B-5122 | None Available |
| SCM9B-5131 | None Available |
| SCM9B-5132 | None Available |
| SCM9B-5141 | None Available |
| SCM9B-5142 | None Available |
| SCM9B-5151 | None Available |



Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

| | |
|---|---|
| SCM9B-5152 | None Available |
| SCM9B-5251 | None Available |
| SCM9B-5252 | None Available |
| SCM9B-5312 | None Available |
| SCM9B-5321 | None Available |
| SCM9B-5322 | None Available |
| SCM9B-5332 | None Available |
| SCM9B-5451 | None Available |
| SCM9B-5452 | None Available |
| SCM9B-A1000-115 | None Available |
| SCM9B-A1000-230 | None Available |
| SCM9B-A2000 | None Available |
| SCM9B-D110 | None Available |
| SCM9B-D111 | None Available |
| SCM9B-D112 | None Available |
| SCM9B-D113 | None Available |
| SCM9B-D114 | None Available |
| SCM9B-D115 | None Available |
| SCM9B-D125 | None Available |
| SCM9B-D131 | None Available |
| SCM9B-D133 | None Available |
| SCM9B-D134 | None Available |
| SCM9B-D135 | None Available |
| SCM9B-D136 | None Available |
| SCM9B-D137 | None Available |
| SCM9B-D138 | None Available |
| SCM9B-D141 | None Available |
| SCM9B-D142 | None Available |
| SCM9B-D143 | None Available |
| SCM9B-D145 | None Available |
| SCM9B-D146 | None Available |
| SCM9B-D151 | None Available |
| SCM9B-D152 | None Available |
| SCM9B-D153 | None Available |
| SCM9B-D154 | None Available |
| SCM9B-D161 | None Available |
| SCM9B-D171 | None Available |
| SCM9B-D172 | None Available |
| SCM9B-D192 | None Available |

3331 East Hemisphere Loop • Tucson, Arizona 85706 • (520) 741-1404 • FAX (520) 741-0762
E-Mail: sales@dataforth.com • Website: www.dataforth.com

Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000

| | |
|---|---|
| SCM9B-H1750 | None Available |
| SCM9B-H1770 | None Available |
| SCM9B-PB08 | None Available |
| SCM9B-PB14 | None Available |
| SCM9B-S300 | None Available |

3331 East Hemisphere Loop • Tucson, Arizona 85706 • (520) 741-1404 • FAX (520) 741-0762
E-Mail: sales@dataforth.com • Website: www.dataforth.com

Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000