Release Notes Dataforth IPEmotion for MAQ20 Dataforth PlugIn

V 01.02.09.0001

- Fixed issues with BRDG1 module. Related to incorrect reset register
- Documented fixes for ISOxx modules and DORLY module

V 01.02.08.0001

- MAQ20-ISOxx added

V 01.02.04.0001

- Adding digital output channels to MAQ20-FRQ
- Adding sleep before reset before reset counter channels in MAQ20-FRQ
- Bugfix timebase MAQ20-FRQ
- Removing 64k and 32k Sample rate in selection for BRDG1
. Changes in notification BRDG1

LRI Distribuída no Brasil pela LRI | vendas@lri.com.br | 51 2129-3000